

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

RECEIVED
FEB 23 2000
DIVISION OF
OIL, GAS AND MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1-98 To (mo./yr.) 1-99
2. DOGM File Number (Mine No): S 13701101
3. Mine Name: Bacon Rock Quarry
4. Mineral(s) Mined (or permitted to mine): Sandstone
5. Type of mine ☐ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
SE 1/4, NE 1/4, ___ 1/4, Section 30, Township 38S, Range 24E,
___ 1/4, ___ 1/4, ___ 1/4, Section ___, Township ___, Range ___
___ 1/4, ___ 1/4, ___ 1/4, Section ___, Township ___, Range ___
7. Name of Operator or Company: Bedrock Stone
8. Permanent Street Address: 1033 N. Grayson Pkwy 3-6
City, State, Zip: Blanding, ut. 84511
Phone: 435-678-3055 Fax: SAME
9. Company Representative (or designated operator):
Name: Eldon E. Virgil
Title: Owner
Business Address: 1033 N. Grayson Pkwy 3-6
City, State, Zip: Blanding, ut. 84511
Phone: 435-678-3055 Fax: SAME
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? _____
3. If yes - how much ore or mineral was mined? Sandstone 3700 Ton

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.
Extracting Sandstone - 3700 Tons Net was moved
no additional surface was disturbed
5. How much **additional acreage** was disturbed during the past year? NONE
6. How much acreage was **reclaimed** during the past year? 460 ft. of slope
7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
Removal of all trash from existing slopes, removing
scattered stone and debris from slopes
8. What is the **total** disturbed acreage of entire project at years end? 3 1/2 acres
9. Briefly summarize any mining and/or reclamation plans for the upcoming year.
To finish quarrying and reclaim 2 acres on the
North side.

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

Eldon E. Virgil

Title of Operator:

owner

Signature of Operator:

[Signature]

Date:

4-16-00

RECEIVED

FEB 23 2000

DIVISION OF
OIL, GAS AND MINING